

McDonald Taylor Ltd

Trading as SJH Consulting

56 Kings Mead
South Nutfield
RH1 5NN

Health & Safety Inspection Report

Organisation	Graham Care Ltd,
Name(s) of Contact	Nicola Delves Colin Midgeley
Address	Seven Mile Lane Wrotham Heath Kent TN15 7RY
Tel No	01732 882282
E Mail	manager@haprwood.co.uk
Date of Inspection	24 th May 2021

Observation	Recommendations	Responsibility	Completed
Immediate Priorities. Resolve within 7 days.			
1	None identified		
High Priorities. Resolve within 1 month			
2	None Identified		
Medium Priorities Resolve within 3 months			
3	External fire escape route.	The external fire escape route is a pathway surrounding the building. Due to the unseasonably inclement weather this year there is a trace of moss on the path. This should be brushed, or jet washed away to make it safe for anyone using the path.	
Low Priorities. Resolve within 6 months			
4	None identified		
Observation			
5	General documents for statutory inspection.	I was very pleased to find that all documentation had been transferred to the online system used in all Graham Care homes. Colin has mastered the system and all certificates of inspection, thorough examination and testing dates were current. The physical inspection of the property did not reveal any problems only one concern listed above. Congratulations to Colin for his maintenance skills.	